




6581-0 ON-BOARD COMPUTER






Figure 1 - Forward of LH Front Wheel Well




Figure 3 - LH Rear of Engine Compartment




Figure 5 - Under LH Side of Front Bumper
(Splash Guard Pulled Down)




Figure 2 - LH Front of Engine Compartment
(Cover Removed)




Figure 4 - LH Rear of Engine Compartment




Figure 6 - Under LH Side of Dash